

# Oil Field Environmental Incident Summary

**Incident:** 20140411132606      **Date/Time of Notice:** 04/11/2014 13:26

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** SIKES STATE 44-16H

**Field Name:** SANISH

**Well File #:** 18247

**Date Incident:** 4/10/2014      **Time Incident:** 13:00

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 154

**Rng:** 91

**Sec:** 16

**Qtr:**

**Location Description:** The fire originated from the flare at the Sikes State 44-16CTB flare. It burned approximately 240' X 150' of pasture in section 16 and 200' X 200' in section 21.

**Submitted By:** Brian Wurm

**Received By:**

**Contact Person:** Brian Wurm  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.3 Mile

**Distance Nearest Water Well:** 0.3 Mile

**Type of Incident:** Fire

**Release Contained in Dike:** No

**Reported to NRC:** No

**Spilled      Units**

**Recovered      Units**

**Followup      Units**

**Oil**

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Extinguished grass fire

**Areal Extent:**

240' X 150' of pasture in section 16 and 200' X 200' in section 21

***Potential Environmental Impacts:***

None noted

***Action Taken or Planned:***

Grass fire burned out without causing further damage. Area was monitored to ensure no further spread from the burned area.

***Wastes Disposal Location:*** No waste disposal anticipated

***Agencies Involved:*** North Dakota State Land Trust

***Updates***

---

***Date:*** 4/12/2014    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Fire off location ignited by location flare. No release of liquids according to the report. Grass fire off location was extinguished. No on-site inspection required in this incident.